




T-shore
Education

Theory Exercises



Co-funded by
the European Union

Erasmus+

Enriching lives, opening minds.

Module:

**Gearbox and Bearing
Maintenance**

Learning scenario:

Gearbox inspection



Atlantic Technological University		Scalda	
Energy Innovation		Skilliant	
Fagskolen Rogaland		Skive College	
Hydrogen Valley		TCNN	
Katapult		Wind Energy Ireland	
Noorderpoort		World Class Maintenance	
POM West-Vlaanderen			



This document has been created as part of the wider T-shore project, co-funded through the European Union's ERASMUS+ programme.



**Co-funded by
the European Union**

Funded by the European Union. Views and opinions expressed are however those of the author(s) only and do not necessarily reflect those of the European Union or the European Education and Culture Executive Agency (EACEA). Neither the European Union nor EACEA can be held responsible for them

Document Information

Project Acronym	T-shore
Project Title	Technical Skills for Harmonised Offshore Renewable Energy
Award Number	Project 101055746
Work Package	WP3,4
Document Title	Gearbox & Bearings TE V01
Primary Author(s)	Krzysztof Komorowski
Co-Author(s)	All partners

Version Control

Version No.	Date	Description
0.1	11.12.2024	New document created
0.2	26.05.2025	Document Update

Copyright

This document was developed under the T-shore project, coordinated by Skilliant. © 2024 – Skilliant. All rights reserved. Licensed to the European Education and Culture Executive Agency (EACEA) under conditions.

Table 1. Participant overview

Name and surname	
Evaluation exercise 1	
Evaluation exercise 2	
Evaluation exercise 3	


1 Theory

1.1 Exercise 1: Gear types


Description: Match the correct names to the pictures of various types of gears.



Answer: _____



Answer: _____



Answer: _____



Answer: _____



Answer: _____



Answer: _____



Answer: _____



Answer: _____




Answer: _____



1.2 Exercise 2: Gear types

Description: Name the correct parts of the gearbox structure.

1. Name of shafts



Answer 1: _____

Answer 2: _____


Answer 3: _____

Answer 4: _____

Answer 5: _____



2. Name of bearings



Answer 1: _____

Answer 2: _____

Answer 3: _____

Answer 4: _____

Answer 5: _____

Answer 6: _____

Answer 7: _____

Answer 8: _____


Answer 9: _____

Answer10: _____





3. Name of Gears



Answer 1: _____

Answer 2: _____

Answer 3: _____

Answer 4: _____

Answer 5: _____

Answer 6: _____

Answer 7: _____

1.3 Exercise 3: Case study

Description: Familiarise yourself with the materials related to Case Study 1 and Case Study 2 concerning gearbox repairs and inspections. Present your opinion and thoughts in a few sentences.

1.3.1 Case study 1.



Wind turbine:

- Nordex N50-800 kW
- Start operation May 18, 2000
- 5 years of warranty
- Gearbox: Flender PEAS 4290.2
- 1 planetary stage, 2 parallel stages
- Version 2 of this type.



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800

Inspection 1

- Inspection on August 20, 2003 (after 3¼ years operation)
- Visual inspection of gearbox through inspection cover.
- Nordex control system:
 - The hand terminal in the nacelle does not always function.
 - When it does not function, the brake cannot be released and the gears can only be inspected in one position.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS

VINDMØLLEFORENING



Case Nordex 800



LSIMS Wheel
Normal running in wear



HSIMS pinion
Indentation marks and
scuffing
from particles

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010


DANMARKS

VINDMØLLEFORENING






Case Nordex 800



HS IMS Wheel
Micro pitting
Two coloured appearance



HS pinion
Micro pitting on the inner half.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

Case Nordex 800

Inspection 1

What can be concluded from this inspection ?

- Wear occurs in the gearbox on the wheel on IMS and the HSS pinion.
- Claim to the manufacturer.
- Inspect the gearbox before end of warranty.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800

Inspection 2

Inspection on April 5, 2005 before end of warranty

- Visual inspection of gearbox through inspection cover.
- Nordex control system:
- The hand terminal in the nacelle does not always function.
- When it does not function, the brake cannot be released
- and the gears can only be inspected in one position.


Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800



LS IMS Wheel
Normal running in
wear




HS IMS pinion
Stand still marks
Indentation marks and
scuffing
from particles

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800



HS IMS Wheel
Micro pitting
Two coloured appearance



HS pinion
Micro pitting on the inner
half.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING

Case Nordex 800

Mobil		20 JUNI 2002		MIDS																													
Mobil Oleanalyse System																																	
<table border="0"> <tr> <td>Model</td> <td>Mobide 6888</td> <td>REXING</td> <td>REX-1-0000</td> </tr> <tr> <td>Adresse</td> <td>Erwinstrasse 1</td> <td>Mobide Ref.</td> <td>-</td> </tr> <tr> <td></td> <td>73300 W</td> <td>Date for ppm</td> <td>14-12-02</td> </tr> <tr> <td>Customer</td> <td>Demaco</td> <td>Oleotype</td> <td>Mobiltype SNC VPP 322</td> </tr> <tr> <td>Manufacturer</td> <td>Demaco</td> <td>Oleant</td> <td>-</td> </tr> <tr> <td>Telefon</td> <td>Customer Telephone:</td> <td>Model</td> <td>Mobide 6888</td> </tr> <tr> <td>Telefax</td> <td>73 33 44 00</td> <td>Ident Nr</td> <td>00110</td> </tr> </table>						Model	Mobide 6888	REXING	REX-1-0000	Adresse	Erwinstrasse 1	Mobide Ref.	-		73300 W	Date for ppm	14-12-02	Customer	Demaco	Oleotype	Mobiltype SNC VPP 322	Manufacturer	Demaco	Oleant	-	Telefon	Customer Telephone:	Model	Mobide 6888	Telefax	73 33 44 00	Ident Nr	00110
Model	Mobide 6888	REXING	REX-1-0000																														
Adresse	Erwinstrasse 1	Mobide Ref.	-																														
	73300 W	Date for ppm	14-12-02																														
Customer	Demaco	Oleotype	Mobiltype SNC VPP 322																														
Manufacturer	Demaco	Oleant	-																														
Telefon	Customer Telephone:	Model	Mobide 6888																														
Telefax	73 33 44 00	Ident Nr	00110																														
ANALYSE/REGULATOR		Automatic resistance																															
System nr		1	3	3																													
Analysedato		14-02-01	23-12-02	15-06-02																													
Machine driven	drifted	3011.91	-	18029																													
Client driven	drifted	-	-	-																													
Starttype (lit.)		-	-	-																													
Vitrus driftance		-	-	-																													
Viskositet (CST 40C)		315	316	315																													
Flammepunkt (C)		180	180	180																													
		-	-	11																													
SW (mg/m ³ /g)		1.14	1.28	1.81																													
Vandtypp		0.3	0.3	0.3																													
Ellimontyp		13	13	28																													
Oxidation		<1	<1	5																													
Udsættelse		0.04	0.05	0.07																													
Jern		34	35	116																													
Aluminium		<1	<1	<1																													
Kobolt		<1	1	2																													
Nickel		3	3	1																													
Molybdæn		9	8	8																													
Kobber		1	<1	1																													
SiO ₂		<1	<1	<1																													
TiO ₂		<1	<1	<1																													
Wolfram		<1	<1	<1																													
Naft		3	3	3																													
Naftgen		<1	<1	<1																													
Vandindhold		<1	<1	<1																													
Resultat olie kan fortsettes arbejde.																																	
Resultat resultat.																																	
Report date: 15-06-02 Report reference: M24847 1 tilladelse til operation til operation, inden vi kan kontakte teknisk afdeling på tel.nr. 42 19 00 00 15-06-02																																	

Oil analyses from
2001 and 2002

Sample no.	1	2	3
Date of analysis	16-02-20 01	03-12-20 01	17-04-20 02
Fe ppm	54	120	146

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMOLLEFORENING



Case Nordex 800

Laurits O. Sengst

LABORATORY REPORT

7009
LINE ID Number

Customer: Nordex 11-9-2004 (01/09/04)
Nordex Energy GmbH
Mr. Hans L. Sonderholm
C.F. Tietgenvej 10
DK-8000 Kolding

Material type: N50
Manufacturer: Nordex
Sample from: Indekstegningsskole
Oil brand name: Mobil 220P 320

Oil analysis results: Actual sample

Lab. Number	21.11.2004	12.11.2004	12.11.2004	12.11.2004
Date taken	21.11.2004	12.11.2004	12.11.2004	12.11.2004
Date service taken	12.11.2004	12.11.2004	12.11.2004	12.11.2004
Hourly rate	16274	16274	16274	16274
Hourly rate last oil change	16274	16274	16274	16274

Oil analysis results: Previous sample

Lab. Number	102179	102179	102179	102179
Date taken	10.03.2004	10.03.2004	10.03.2004	10.03.2004
Date service taken	10.03.2004	10.03.2004	10.03.2004	10.03.2004
Hourly rate	16274	16274	16274	16274
Hourly rate last oil change	16274	16274	16274	16274

WEAR METALS

Unit	mg/kg	mg/kg	mg/kg	mg/kg
Fe	84	81	81	84
Cr	1	1	1	1
Al	0	0	0	0
Aluminum	0	0	0	0
Na	1	1	1	1
Copper	4	4	4	4
Lead	1	1	1	1
Insoluble	0	0	0	0
POWDER	0	0	0	0

CONTAMINATION

Unit	mg/kg	mg/kg	mg/kg	mg/kg
Black, total	10	12	10	9
Black, K	0	0	0	0
Black, R	2	1	1	1
Black, S	1	1	1	1
Black, T	1	1	1	1
Black, U	1	1	1	1
Black, V	1	1	1	1
Black, W	1	1	1	1
Black, X	1	1	1	1
Black, Y	1	1	1	1
Black, Z	1	1	1	1

GIL CONDITION

Unit	mg/kg	mg/kg	mg/kg	mg/kg
Viscosity at 40°C	212.23	212.23	212.23	212.23
Viscosity at 100°C	33.83	33.83	33.83	33.83
Viscosity index	68	68	68	68
Cloudiness	7	7	7	7

ADDITIONAL TESTS

Unit	mg/kg	mg/kg	mg/kg	mg/kg
Cadmium	0	0	0	0
Mercury	0	0	0	0
Barium	0	0	0	0
Strontium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0

ADDITIONAL TESTS

Unit	mg/kg	mg/kg	mg/kg	mg/kg
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0
Antimony	0	0	0	0
Vanadium	0	0	0	0
Chromium	0	0	0	0
Iron	0	0	0	0
Copper	0	0	0	0
Lead	0	0	0	0
Aluminum	0	0	0	0
Silicon	0	0	0	0
Calcium	0	0	0	0
Magnesium	0	0	0	0
Sodium	0	0	0	0
Potassium	0	0	0	0
Phosphorus	0	0	0	0
Sulfur	0	0	0	0
Chlorine	0	0	0	0
Fluorine	0	0	0	0
Bromine	0	0	0	0
Iodine	0	0	0	0



Case Nordex 800

After Inspection 2

- The owner started a legal proceeding against Nordex.
- A technical experts was found to evaluate the questions about the Gearbox:
 - Was the condition of the gearbox at the time of end of warranty in a state that could be expected after 5 years of operation ?
 - If not, what is the reason ?

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING



Case Nordex 800

Inspection 3

Inspection on May 2, 2007 by the expert

- Nordex staff dismantled the top of the gearbox.
- Nordex staff used a hand pump to loosen the brake.
- Visual inspection of gearbox. Endoscope available.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING





Case Nordex 800



HS IMS pinion
Marks from two running
positions



HS IMS pinion
Marks from two running
positions

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING

Case Nordex 800

Particles found in the bottom
of the gearbox with a magnet.



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING






Case Nordex 800

Roller cage with heavy damage.
Collar on NJ-bearing broken off.



007 12:44 3976



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29,

Case Nordex 800

Inspection 3

What can be concluded from this inspection ?

- The wheel is loose on IMS.
- The wheel has probably been loose since installation. This is the cause of the two-coloured appearance micro pitting and the high iron content.
- The collar on the NJ-bearing on IMS has broken off.
- When the wheel is loose the axial forces on the teeth will force the wheel towards the rotor-end bearing giving extra load on the collar.

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800



Inspection 4

In workshop after
disassembly

HS IMS wheel.

Fretting corrosion on the bore surface +0,2 mm

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800



HS IMS.

Fretting corrosion on the
surface



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010





Case Nordex 800

IMS. Rotor-end bearing
The collar is broken off on the
entire circumference



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800

- What did you learn from this case ?

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case study 2.





Case Nordex 1300

- Nordex N60-1300 kW
- Gearbox: Eickhoff CPNHZ-190 G 043780X
- Gearbox is damaged and replaced
- Gearbox is taken apart in Eickhoffs workshop
- Inspection by owners representative and insurance company

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 1300

HS IMS wheel
Scuffing in bore.

The wheel is
pressed on the
shaft, and no key
is used.



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010





Case Nordex 1300




HS IMS Pinion.

Damage on 2
teeth.

Case Nordex 1300



HS IMS wheel has worn
3 bolt heads ~10 mm.





Case Nordex 1300




High speed pinion

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING

Case Nordex 1300



Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010

DANMARKS
VINDMØLLEFORENING





Case Nordex 1300

Insurance company claims:

- The wheel has been loose on the shaft
- The bearings on the LSIMS are not damaged
- The bolt are worn 10 mm, so the wheel have moved on the shaft several times
- The damage on the 2 teeth is started with pitting and the material has cracked off due to this pitting
- The damaged is not covered by insurance

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 1300

Owners representative claims:

- The wheel has moved on the shaft only once. After that the damage in the bore show that the 2 parts are grated together
- The missing material has scaled off first, and then the pitting is formed. One extreme load has deformed the teeth and started cracks
- The extreme load has deformed the casing, which explains the 10 mm wear on the bolt heads
- The marks on the HSS proofs only one move of the wheel
- The insurance company covered the damage

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2010



Case Nordex 800

- What did you learn from this case ?

Gearbox Troubleshooting, Inspection & Maintenance, Smøla, Norway, September 28, 29, 30 - 2019



Answer for both Case study 1 and Case study 2: _____

[illegible]



Co-funded by the European Union

The T-shore project is funded through the the
Erasmus+ Centres of Vocational Excellence
(CoVEs) call 2021

Acknowledgements

We would like to extend our sincere thanks to all the project partners for their invaluable contributions to this report and their dedicated work on the T-shore project.

Our deepest appreciation also goes to all T-shore stakeholders, particularly the members of the regional Centres of Vocational Excellence (CoVEs), whose ongoing efforts are instrumental in driving the success of this initiative.

t-shore.eu
tshore.eu@gmail.com