


Erasmus+

Enriching lives, opening minds.

Equipment Checklist

Example for Instructor



Module:

Gearbox and Bearing
Maintenance
Learning scenario:
Gearbox inspection



ENERGY ∴NNOVATION



Atlantic Technological University		Scalda	
Energy Innovation	#	Skilliant	
Fagskolen Rogaland	#	Skive College	+
Hydrogen Valley	==	TCNN	
Katapult	-	Wind Energy Ireland	
Noorderpoort		World Class Maintenance	
POM West-Vlaanderen			



























This document has been created as part of the wider T-shore project, co-funded through the European Union's ERASMUS+ programme.



Funded by the European Union. Views and opinions expressed are however those of the author(s) only and do not necessarily reflect those of the European Union or the European Education and Culture Executive Agency (EACEA). Neither the European Union nor EACEA can be held responsible for them

Document Information

Project Acronym	T-shore
Project Title	Technical Skills for Harmonised Offshore Renewable Energy
Award Number	Project 101055746
Work Package	WP3,4
Document Title	Gearbox inspection EC V02
Primary Author(s)	
Co-Author(s)	All partners

Version Control

Version No.	Date	Description
0.1	22.11.2024	New version of instruction, cosmetic changes
0.2	28.07.2023	New instruction created
0.3	26.05.2025	Document Update

Note This is a fictive generic equipment checklist intended for training purposes and therefore may vary from the equipment checklist provided by a company. It is important that a technician always read and fill checklist carefully prior to any task.

Copyright

This document was developed under the T-shore project, coordinated by Skilliant. © 2024 – Skilliant. All rights reserved. Licensed to the European Education and Culture Executive Agency (EACEA) under conditions.





1 Documentation overview

Table 1. Documentation overview

Order number	53337
Order name	WTG 23_Gearbox insp.
Priority	Low
WTG serial number, range	34541
Site name	Valhalla wind farm
Date	22.12.2023
Reporting by	Chris Connor
Site Supervisor	Mark Wahlberg

2 Equipment checklist

Table 2. Equipment checklist

Component name	Serial number	Visual condition	Working condition	Comment
Mechanical gloves	n/a	Good, no visual signs of damage	n/a	n/a
Electrical torque wrench	94383207	Good, no visual signs of damage, calibration label visible and correct	Working correctly	Needs to be cleaned





Erasmus + Enriching lives, opening minds.

Additional Notes:					
Employee Signature:					
Date:					
Supervisor Signature:					
Date:					



Co-funded by the European Union

The T-shore project is funded through the the Erasmus+ Centres of Vocational Excellence (CoVEs) call 2021

Acknowledgements

We would like to extend our sincere thanks to all the project partners for their invaluable contributions to this report and their dedicated work on the T-shore project.

Our deepest appreciation also goes to all T-shore stakeholders, particularly the members of the regional Centres of Vocational Excellence (CoVEs), whose ongoing efforts are instrumental in driving the success of this initiative.

t-shore.eu tshore.eu@gmail.com