




T-shore
Education

Equipment Checklist:

Example for Instructor



Co-funded by
the European Union

Erasmus+

Enriching lives, opening minds.

Module:

Hydraulic Brake System

Learning scenario:

Brake Disc Check



Atlantic Technological University		Scalda	
Energy Innovation		Skilliant	
Fagskolen Rogaland		Skive College	
Hydrogen Valley		TCNN	
Katapult		Wind Energy Ireland	
Noorderpoort		World Class Maintenance	
POM West-Vlaanderen			



This document has been created as part of the wider T-shore project, co-funded through the European Union's ERASMUS+ programme.



**Co-funded by
the European Union**

Funded by the European Union. Views and opinions expressed are however those of the author(s) only and do not necessarily reflect those of the European Union or the European Education and Culture Executive Agency (EACEA). Neither the European Union nor EACEA can be held responsible for them.

Document Information

Project Acronym	T-shore
Project Title	Technical Skills for Harmonised Offshore Renewable Energy
Award Number	Project 101055746
Work Package	WP3,4
Deliverable	LSC – Equipment Checklist: Example for Instructor
Document Title	Hydraulic Brake System Equipment Checklist: Example for Instructor
Primary Author(s)	Klaas Minne, Benedikte Tryhou
Co-Author(s)	All partners

Version Control

Version No.	Date	Description	Prepared by	Checked by
01	15.04.2025	New instruction created	KM	BT
05	05.2025	Document Updated	DH	

***Note** This is a fictive generic equipment checklist intended for training purposes and therefore may vary from the equipment checklist provided by a company. It is important that a technician always read and fill checklist carefully prior to any task.*

Copyright

This document was developed under the T-shore project, coordinated by Skilliant. © 2024 – Skilliant. All rights reserved. Licensed to the European Education and Culture Executive Agency (EACEA) under conditions

1 Documentation overview

Table 1. Documentation overview

Order number	
Order name	
Priority	
WTG serial number, range	
Site name	
Date	
Reporting by	
Site Supervisor	

2 Equipment checklist

Table 2. Equipment checklist

Component name	Serial number	Visual condition	Working condition	Comment
safety gloves (resistant to hydraulic oil)	n/a	Good, no visual signs of damage	n/a	n/a
Nacelle	19081	Good, no visual signs of damage	Working correctly	None
Lockout device	n/a	Good, no visual signs of damage	n/a	n/a
padlock	n/a	Good, no visual signs of damage	n/a	n/a
tag	n/a	Good, no visual signs of damage	n/a	n/a



Goggles	n/a	Good, no visual signs of damage	n/a	n/a
Measuring cup	n/a	Good, no visual signs of damage	n/a	n/a
Clear plastic tubing	n/a	Good, no visual signs of damage	n/a	n/a
1/4" wrench	n/a	Good, no visual signs of damage	Working correctly	None

Additional Notes:

Employee Signature:

Date:

Supervisor Signature:

Date:





Co-funded by the European Union

The T-shore project is funded through the the
Erasmus+ Centres of Vocational Excellence
(CoVEs) call 2021

Acknowledgements

We would like to extend our sincere thanks to all the project partners for their invaluable contributions to this report and their dedicated work on the T-shore project.

Our deepest appreciation also goes to all T-shore stakeholders, particularly the members of the regional Centres of Vocational Excellence (CoVEs), whose ongoing efforts are instrumental in driving the success of this initiative.

t-shore.eu
tshore.eu@gmail.com